

FORM FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

1. Name of the School
2. Location
3. Plot Area
4. Plinth Area
5. No. of Stories
6. Year of Construction

ST KABIR CONVENT SEN SEC SCHOOL
 ADJOINING ADRESH UNIVERSITY, DHUKHIA KUMAR
 BATHINDA
 4.78 ACER
 1200 Sq Mtr.
 2
 2010

7. Whether the building has been constructed under the supervision of the qualified Engineer, if so.

- a) Name of the Engineer with qualification
- b) Address

Er BHUPINDER KUMAR
 M.TECH CIVIL
 MCB-22-04562 (F.FLOOR)
 OPPOSITE ELECTRIC GRID
 NEAR 100 FT CHOWK POWER HOUSE ROAD
 BATHINDA.

- c) Set of structural drawing used in construction

8. Whether the building has been constructed for the purpose of: -

- a) School : (Yes/No) ✓
- b) Residential purpose (or) : (Yes/No) ✓
- c) Converted for school : (Yes/No) ✓

9. Material used for Roofs: -

- a) R.C.C. Slab : (Yes/No) ✓
- b) R.S. joints & Battens : (Yes/No) ✓
- c) Wooden Joints & Battens : (Yes/No) ✓

10. Material used for Walls: -

- a) Mud Mortar : (Yes/No) ✓
- b) Cement Mortar : (Yes/No) ✓
- c) Plaster :
 - Lime Mortar : (Yes/No) ✓
 - Cement Mortar : (Yes/No) ✓

11. Flooring: -

- a) Conglomerate : (Yes/No) ✓
- b) Terrazo : (Yes/No) ✓
- c) Brick Paving : (Yes/No) ✓

12. A detailed drawing indicating dimensions of the rooms & location of doors and windows is attached.

13. General

- i) In case of double story building 1.5 meter width upstairs are Constructed or not : (Yes/No) ✓



ii) Whether all class room are provided two door : (Yes / No) ✓
system.

iii) Whether fire safety measures have been : (Yes / No) ✓
adopted and are in working condition.

Principal
St. ~~K...~~ Senior
Seco...
Bhuchio (Bathinda)

Dated: _____ Signature of Principal with school stamp.

(For the use of the PWD B&R department).

a) I Er Anshu Garg S.D.E. alongwith Daljeet Singh J.E.
have visited this school on 6/6/24 and have inspected It from all angles of safety
and found it fit for normal use as school building.

b) In case any addition, alteration, extension or modification of this building is to be carried
out, it should be carried out under the supervision of technical qualified Engineer, and
after its completion, this certificates may again be obtained from the undersigned.

c) In case the building is affected by flood or if there is settlement to walls foundations,
edging or roof, immediate inspection of the undersigned be arranged to check the
stability and safety of the building.

d) The building can be safely occupied for normal use upto 31-3-2025

e) Inspection fee has been deposited by the school vide G.R. No. 1745873 dt.
12/6/24 amounting to Rs. 10,000/-

Countersigned

[Signature]
Sub Divisional Engineer,
Sub Divisional Engineer
Provl. Sub Divn. No.1, PWD B&R
Bathinda

Executive Engineer,